

TITLE:

TITLE:	ROOF A	<u>SSEMBLY</u>	
VERSION:	V2.2		
DATE PUBLISHED:	06/23/2	22	
DEFINITION:	The exter	rnal upper cov	ering of a house or other building.
PURPOSE:			m the exterior elements, as well as collect and redirect the accumulation of precipitation from the roof or drainage system.
COMMON COMPONENTS:	Roof cove	ering; Drain; G	utter; Downspout; Flashing; Roof ventilation; Scupper; Eaves; Soffits; Fascia
LOCATION:		Unit	None
		Inside	None
	\boxtimes	Outside	On top of building
MORE INFORMATION:	None		
DEFICIENCY I:		w of water fro	m a roof drain, gutter, or downspout.
LOCATION:	Outside		
DEFICIENCY 2:	Gutter compo	nent is damag	ed, missing, or unfixed.
LOCATION:	Outside		
DEFICIENCY 3:	Roof surface	has standing w	vater.
LOCATION:	Outside		
DEFICIENCY 4:	Substrate is e	xposed.	
LOCATION:	Outside		
DEFICIENCY 5:	Roof assembly	has a penetr	ative hole.
LOCATION:	Outside		
DEFICIENCY 6:	Roof assembly	, is damaged.	
LOCATION:	Outside		

Deficiency I — Outside: Restricted flow of water from a roof drain, gutter, or downspout.

DEFICIENCY CRITERIA: Debris is limiting the ability of water to drain; water may not be present.

OR

An area of approximately 25 square feet of ponding water is located above the drain.

HEALTH AND SAFETY DETERMINATION:

Moderate

The Moderate Health and Safety category includes deficiencies that, if evident in the home or on the property, present a moderate risk of an adverse medical event requiring a healthcare visit; cause temporary harm; or if left untreated, cause or worsen a chronic condition that may have long-lasting adverse health effects; or that the physical security or safety of a resident or their property could be compromised.

CORRECTION TIMEFRAME:

30 days

HCV PASS / FAIL:

Fail

HCV CORRECTION TIMEFRAME:

30 days

INSPECTION PROCESS:

OBSERVATION: - Look at the roof drain, gutter, or downspout for ponding water.

- Look for evidence of clogging (e.g., debris, leaves, or soil).

REQUEST FOR HELP: - Non

ACTION: - If visually accessible, inspect the roof drain and gutters.

MORE INFORMATION: - It may not be possible to gain access to the roof in single family units.

- Ponding may be hard to determine if it has not been raining; in this situation, the inspector is unable to cite a

deficiency.

DEFICIENCY 2 — OUTSIDE: GUTTER COMPONENT IS DAMAGED, MISSING, OR UNFIXED.

DEFICIENCY CRITERIA: Gutter component is damaged (i.e., visibly defective; impacts functionality).

OR

Gutter component is missing (i.e., evidence of prior installation, but now not present or is incomplete).

OR

Gutter component is unfixed.

HEALTH AND SAFETY DETERMINATION: Moderate The Moderate Health and Safety category includes deficiencies that, if evident in the home or

on the property, present a moderate risk of an adverse medical event requiring a healthcare visit; cause temporary harm; or if left untreated, cause or worsen a chronic condition that may have long-lasting adverse health effects; or that the physical security or safety of a resident or

their property could be compromised.

CORRECTION TIMEFRAME:

30 days

HCV PASS / FAIL:

Fail

HCV CORRECTION TIMEFRAME:

30 days

INSPECTION PROCESS:

OBSERVATION: - Look at the gutter system to detect any:

- Gutter components that are damaged (i.e., visibly defective; impacts functionality).

- Gutter components that are missing (i.e., evidence of prior installation, but now not present or is incomplete).

- Gutter components that are unfixed (i.e., pulled away from the fascia or roofing structure).

REQUEST FOR HELP: -

- None

ACTION:

- None

MORE INFORMATION:

- Gutters may not be present on all properties.

Deficiency 3 - Outside: Roof surface has standing water.

DEFICIENCY CRITERIA: Water ponding in an area approximately 25 square feet or greater on a flat roof surface not near a drain or scupper.

HEALTH AND SAFETY DETERMINATION: Moderate The Moderate Health and Safety category includes deficiencies that, if evident in the home or

on the property, present a moderate risk of an adverse medical event requiring a healthcare visit; cause temporary harm; or if left untreated, cause or worsen a chronic condition that may have long-lasting adverse health effects; or that the physical security or safety of a resident or

their property could be compromised.

CORRECTION TIMEFRAME: 30 days

HCV PASS / FAIL: Fail

HCV CORRECTION TIMEFRAME: 30 days

INSPECTION PROCESS:

OBSERVATION: - Look to see if the building has a flat roof; if not, disregard this deficiency.

- Look for ponding water on the roof that isn't located above a drain or scupper.

REQUEST FOR HELP: - None

ACTION: - Measure the ponding.

MORE INFORMATION: - None



Deficiency 4 - 0utside: Substrate is exposed.

DEFICIENCY CRITERIA: Any amount of substrate is exposed.

HEALTH AND SAFETY DETERMINATION: Moderate The Moderate Health and Safety category includes deficiencies that, if evident in the home or

on the property, present a moderate risk of an adverse medical event requiring a healthcare visit; cause temporary harm; or if left untreated, cause or worsen a chronic condition that may have long-lasting adverse health effects; or that the physical security or safety of a resident or

their property could be compromised.

CORRECTION TIMEFRAME:

30 days

HCV PASS / FAIL:

Fail

HCV CORRECTION TIMEFRAME:

30 days

INSPECTION PROCESS:

OBSERVATION: - Look at the roof surface for evidence of exposed substrate (e.g., missing or damaged shingles, tiles, or membrane).

REQUEST FOR HELP: - None

ACTION: - None

MORE INFORMATION: - It may be difficult to determine if there is exposed substrate in single family homes.

Deficiency 5 - Outside: Roof assembly has a penetrative hole.

DEFICIENCY CRITERIA: Penetrative, unintentional hole of any size is found.

OR

Intentional, penetrative hole of any size is found and is not covered by vents or screens.

HEALTH AND SAFETY DETERMINATION: Moderate The Moderate Health and Safety category includes deficiencies that, if evident in the home or

on the property, present a moderate risk of an adverse medical event requiring a healthcare visit; cause temporary harm; or if left untreated, cause or worsen a chronic condition that may have long-lasting adverse health effects; or that the physical security or safety of a resident or

their property could be compromised.

CORRECTION TIMEFRAME:

30 days

HCV PASS / FAIL:

Fail

HCV CORRECTION TIMEFRAME:

30 days

INSPECTION PROCESS:

- Look at the roof's soffits, eaves, fascia, and roof deck for holes—both intentional and unintentional—that penetrate

completely through the component's material.

REQUEST FOR HELP:

OBSERVATION:

- None

ACTION:

- None

MORE INFORMATION:

- None



Deficiency 6 - 0utside: Roof assembly is damaged.

DEFICIENCY CRITERIA: Roof assembly is damaged (i.e., visibly defective; impacts functionality), causing one or more components to become

unstable.

HEALTH AND SAFETY DETERMINATION: Moderate The Moderate Health and Safety category includes deficiencies that, if evident in the home or

on the property, present a moderate risk of an adverse medical event requiring a healthcare visit; cause temporary harm; or if left untreated, cause or worsen a chronic condition that may have long-lasting adverse health effects; or that the physical security or safety of a resident or

their property could be compromised.

CORRECTION TIMEFRAME:

30 days

HCV PASS / FAIL:

. Fail

HCV CORRECTION TIMEFRAME:

30 days

INSPECTION PROCESS:

OBSERVATION: - Look at the roof's perimeter soffits, eaves, fascia, and roof deck for damage.

REQUEST FOR HELP:

- None

ACTION:

- None

MORE INFORMATION:

- None



SUMMARY OF CHANGES

TITLE: ROOF ASSEMBLY

VERSION: V2.2

DATE PUBLISHED: 06/23/22

Field	Change	Version	Date
	Abbreviated published version	V2.2	2022-06-23
Name Variants	Removed from published version		
Common Materials	Removed from published version		
Rationale	Removed from published version		
Tools or Equipment	Removed from published version		
Deficiency I		V2.2	2022-06-23
Health and Safety Determination	Outside: Relabeled from "Standard" to "Moderate"		
Deficiency 2		V2.2	2022-06-23
Health and Safety Determination	Outside: Relabeled from "Standard" to "Moderate"		
Deficiency 3		V2.2	2022-06-23
Health and Safety Determination	Outside: Relabeled from "Standard" to "Moderate"		
Deficiency 4		V2.2	2022-06-23
Health and Safety Determination	Outside: Relabeled from "Standard" to "Moderate"		
Deficiency 5		V2.2	2022-06-23
Health and Safety Determination	Outside: Relabeled from "Standard" to "Moderate"		
Deficiency 6		V2.2	2022-06-23
Health and Safety Determination	Outside: Relabeled from "Standard" to "Moderate"		
	Copyedits	V2.1	2021-04-02
Common Components	Copyedits	V2.0	2020-10-28
Deficiency I		V2.0	2020-10-28
Title	Revised title		



Health and Safety Determination	Added standardized description		
HCV Pass / Fail	Field added; response input as "Fail"		
Rationale	Copyedits		
Deficiency 2		V2.0	2020-10-28
Title	Revised title		
Deficiency Criteria	Revised deficiency criteria		
Health and Safety Determination	Added standardized description		
HCV Pass / Fail	Field added; response input as "Fail"		
Rationale	Copyedits		
Deficiency 3		V2.0	2020-10-28
Health and Safety Determination	Added standardized description		
HCV Pass / Fail	Field added; response input as "Fail"		
Rationale	Copyedits		
Deficiency 4		V2.0	2020-10-28
Health and Safety Determination	Added standardized description		
HCV Pass / Fail	Field added; response input as "Fail"		
Rationale	Copyedits		
Deficiency 5		V2.0	2020-10-28
Deficiency Criteria	Copyedits		
Health and Safety Determination	Added standardized description		
HCV Pass / Fail	Field added; response input as "Fail"		
Rationale	Copyedits		
Deficiency 6		V2.0	2020-10-28
Title	Copyedits		
Deficiency Criteria	Copyedits		
Health and Safety Determination	Added standardized description		
HCV Pass / Fail	Field added; response input as "Fail"		



Deficiency 3	Previously deficiency 2 Separated by inspectable location — Outside	VI.3	2020-07-31
Tools or Equipment	Field added to deficiency		
Inspection Process	Added observation, request for help, action, and more information		
Rationale	Added rationale categories, types, and explanations; added standardized codes and descriptions		
HCV — Correction Timeframe	Field added; response input as "Within 30 days"		
Correction Timeframe	Field added; response input as "Within 30 days"		
Health and Safety Determination	Added "Standard" determination; added standardized description		
Deficiency Criteria	Added deficiency criteria		
Title	Added title; added inspectable location		
Deficiency 2	Added by inspectable location — Outside	VI.3	2020-07-31
Tools or Equipment	Field added to deficiency; response revised		
Inspection Process	Revised observation, request for help, action, and more information		
Rationale	Revised rationale categories, types, and explanations; added standardized codes and descriptions		
HCV — Correction Timeframe	Field added; response input as "Within 30 days"		
Correction Timeframe	Field added; response input as "Within 30 days"		
Health and Safety Determination	Added standardized description		
Deficiency Criteria	Revised deficiency criteria		
Title	Revised title; added inspectable location		
Deficiency I	Separated by inspectable location — Outside	VI.3	2020-07-31
More Information	Field added	VI.3	2020-07-31
Common Materials	Revised common materials	VI.3	2020-07-31
Name Variants	Revised name variants	VI.3	2020-07-31
Purpose	Field added	VI.3	2020-07-31
Definition	Revised definition	VI.3	2020-07-31
Overall Formatting	Complete rework of document format and layout	VI.3	2020-07-31
A H.F. (*)		W1 3	3030 07 31

Title	е	Revised title; added inspectable location		
Неа	alth and Safety Determination	Added standardized description		
Con	rection Timeframe	Field added; response input as "Within 30 days"		
HCV	V — Correction Timeframe	Field added; response input as "Within 30 days"		
Rati	ionale	Revised rationale categories, types, and explanations; added standardized codes and descriptions		
Insp	pection Process	Revised observation, request for help, action, and more information		
Too	ols or Equipment	Field added to deficiency; response revised		
Deficiency 4		Previously deficiency 3 Separated by inspectable location — Outside	VI.3	2020-07-31
Title	е	Added inspectable location		
Неа	alth and Safety Determination	Added standardized description		
Con	rection Timeframe	Field added; response input as "Within 30 days"		
HCV	V — Correction Timeframe	Field added; response input as "Within 30 days"		
Rati	ionale	Revised rationale categories, types, and explanations; added standardized codes and descriptions		
Insp	pection Process	Revised observation, request for help, action, and more information		
Too	ols or Equipment	Field added to deficiency; response revised		
Deficiency 5		Previously deficiency 4 Separated by inspectable location — Outside	VI.3	2020-07-31
Title	е	Added inspectable location		
Defi	ficiency Criteria	Revised deficiency criteria		
Неа	alth and Safety Determination	Added standardized description		
Con	rection Timeframe	Field added; response input as "Within 30 days"		
HCV	V — Correction Timeframe	Field added; response input as "Within 30 days"		
Rati	tionale	Revised rationale categories, types, and explanations; added standardized codes and descriptions		
Insp	pection Process	Revised request for help, action, and more information		-
Too	ols or Equipment	Field added to deficiency; response revised		
Deficiency 6		Previously deficiency 5 Separated by inspectable location — Outside	VI.3	2020-07-31



Title	Revised title; added inspectable location
Deficiency Criteria	Revised deficiency criteria
Health and Safety Determination	Added standardized description
Correction Timeframe	Field added; response input as "Within 30 days"
HCV — Correction Timeframe	Field added; response input as "Within 30 days"
Rationale	Revised rationale categories, types, and explanations; added standardized codes and descriptions
Inspection Process	Revised request for help, action, and more information
Tools or Equipment	Field added to deficiency; response revised